

# **E911 Phase II Carrier Implementation Report**

## **Background/Contact Information:**

### **Carrier Identifying Information:**

Tracy Corporation II  
TRS: 809622

### **Contact Information:**

Michael J Tracy  
President  
1225 Sage Street  
Gering, NE 69341  
Phone 308-436-4090  
Fax 308-436-7101  
[mtracy@tlxt.net](mailto:mtracy@tlxt.net)

## **E911 Phase II Location Technology Information:**

### **Type of Technology:**

Tracy Corporation II will be deploying handset solutions to cover the requirements of the Enhanced 911 Phase II. At present time Tracy Corporation II is unaware of any technology which has been proven in independent, scientifically valid trials to meet the Commission's requirements.

Tracy Corporation II has not chosen a vendor(s) for any equipment purchases at date of this filing. The company is currently not supplying service to the public.

### **Testing and Verification:**

Tracy Corporation II has not conducted any test of Phase II technology. The company will adopt testing and verification methods and procedures based on sound practices and will be incorporated into routine testing of the wireless network by company technicians.

### **Implementation Details and Schedule:**

Tracy Corporation II strategy will be to purchase the required equipment and services on the competitive market and deploy the same in accordance with the Commission's rules. Tracy Corporation II is aware that the Commission's rule requires the deployment of Phase II system even if none exists which fully meets the Commission's accuracy requirements.

### **PSAP Interface:**

We will incorporate any required industry standards.

**Existing Handsets:**

Tracy Corporation II is currently not supplying wireless service to the public. Therefore, there are no existing handsets in our public service to upgrade or replace.

**Location of Non-compliant Handsets:**

There are no existing handsets in Tracy Corporation II public service.

**Other Information:**

Tracy Corporation is making every effort to comply with the Phase II E911 requirements and will continue this effort in accordance to the Commission's rules.